

RAIL Top 25 1082- IGV Arm Bearing Failure

Initiator: Brian Reed

Owner: John Pursell

Initiation Date: 5/15/2022

Moved to Top 25: APR 2024

Original Commit Date: NA

Problem Description:

- Wear of IGV/CGV arms result in loss of spherical bearings
- Excessive bearing loss can contribute to compressor surge

Criteria to Close:

- Honeywell to develop and release improved IGV arm to prevent bearing failure

Status & Dates:

- Released SB 72-9001 to address bearing retention in service
- Incorporated interim SB solution into production at engine
- All LMMs were revised to allow fly-on for 25 hrs with one to ten uniballs missing

Next Steps:

- Corrective action underway
- Improved configuration selected – 3033050-4
- Testing complete
- Test results and certification reports are being prepared for review
- Service bulletin estimated in Q4 2025 based on hardware availability
- Redesign can be mixed with original configuration

Estimated Completion Date: Q2 2025

% Completed: 70

Source: GCC



Current 3033050-4

Affected OEMs: Bombardier, Embraer, Textron, Gulfstream

Impacted Regions: APAC; EMEA, Americas

Initiator: Brian Reed

Owner: Cameron Lewis

Initiation Date: 11/11/2022

Moved to Top 25: Nov 2022

Original Commit Date: NA

Problem Description:

High occurrences of MIO detected in SOAP samples; this includes metal findings that may require maintenance activities. Currently evaluating two potential separate sources for Fe and Al in the oil. This appears to be unique to the -150[CL].

Criteria to Close:


- Determine a way to explain or reduce the levels of high Fe and Al found in SOAP sample data

Status & Dates:

- Elevated Fe RCCA – Complete
 - Loose installation of the idler gear mating bushing into the gearbox housing can cause the gear not track as designed and rub with the adjacent surface.
 - OEM drawings and aftermarket CMMs are updated to ensure bushing is cooled and gearbox heated for slip fit at installation, preventing bore damage. Inspection criteria added to CMM for this condition (released Feb 2025)
- Elevated Al RCCA – In progress
 - Further review of shop findings in process to evaluate planetary pin damage/failure and RCCA
 - Evidence of wear through the anodize on the planetary housing is cause of rise in Al levels
 - No indications that pin damage and high Fe levels from bushing/gear rubbing are related

Estimated Completion Date: Q3 2025

% Completed: 75

Source: GCC**Affected OEMs: Bombardier****Impacted Regions: APAC; EMEA; Americas**

RAIL Mechanical Queue 1084- 36-150(EMB) LOP Switch

Initiator: Brian Reed

Owner: Cameron Lewis

Initiation Date: April 2024

Moved to Top 25:NA

Original Commit Date: NA

Problem Description:

3876001-4 Low Oil Pressure switches are failing frequently on the 36-150[EMB] APUs, resulting in No-start and AOG and is a top delay and cancelation driver

Criteria to Close:

- Honeywell to improve the robustness of the -4 LOP switch
 - Improve O-ring to prevent internal oil leakage
 - New internal o-ring selected with improved thermal capability and improved compatibility with APU oils
 - Improve switch body to prevent twisting due to torquing of the hex and body fittings
 - Added extra screw in lower section next to hex nut to increment torque capability.
 - Body structure updates to improve robustness
- There will be no change to the HON P/N; supplier part number will change from 7G1202 to 7G1247. A S/N cut in point will be made with no overlap between the two supplier P/Ns.



Status & Dates:

- HON-CCS (supplier) fault tree & root cause investigation: April 2024
- Fault tree: May 2024
- Root cause approval: May 2024
- Component drawing red lines: May 2024
- CCS Design Changes: June 2024
- Design change PDR: August 2024
- Test Hardware Manufacturing: May 2025
- Design Change CDR: May 2025
- Supplier completion of qual testing: June 2025
- Production cut in: Q4 2025

Estimated Completion Date: Q4 2025

% Completed: 60

Source: GCC



Affected OEMs: Embraer, Textron

Impacted Regions: Americas

RAIL Top 25 1085- W5 Wire Harness Issues – 3034427-3

Initiator: Brian Reed

Owner: John Pursell

Initiation Date: 11/15/2023

Moved to Top 25: APR 2024

Original Commit Date: NA

Problem Description:

- Increased quantity of W5 harnesses are being rejected

Criteria to Close:

- Understand cause of rejections and identify corrective action

Status & Dates:

- Harness from engine 136470 has been returned to supplier (Fokker)
- No fault found during two tests - Static and dynamic

Hurdles:

- Lack of specifics (resistance values, inspection results, etc.) during field investigation (grip it and rip it)
- Field investigation (ohmmeter, megger, visual) cannot always identify an issue caused by operational inputs – vibration / heat & expansion


Next Steps:

- Service Information Letter issued
 - SIL D202401004213 Issued Feb 2, 2024
 - “A Discussion Regarding the AS907 Wire Harnesses; Issues and Investigation”
 - Requests specifics; provides investigation steps
- Service bulletin to apply self-vulcanizing silicone tape to surge bleed valve electrical connectors
 - SBV B is near inner fan bypass panel air scoop
 - Subject to water, dirt, etc.
 - Service bulletin in sign off – target Q2 2025
- Will be incorporated into new engine production

Estimated Completion Date: Q4 2024

% Completed: 95

Source: GCC



Affected OEMs: Bombardier, Embraer, Textron, Gulfstream

Impacted Regions: APAC; EMEA; Americas

RAIL Top 25 1086- AS907 Thrust Reverser (TR) Long-Term Solution

Initiator: GCC

Owner: John Pursell

Initiation Date: Apr 2024

Moved to Top 25: Apr 2024

Original Commit Date: NA

Problem Description:

The GCC committee has requested HON to provide a long-term solution for the AS907 Thrust Reverser coating issues

Criteria to Close:

- Honeywell to develop a long-term solution for the AS907 thrust reverser for fielded engines

Status & Dates:



Honeywell TR Improvement Initiative (for STC Incorporation)

- Thrust Reverser concept development
 - TR Doors composite with embedded titanium interfaces
 - TR Beams dual-pathed with an all-titanium version and a composite/titanium hybrid both being considered
- Replace painted aluminum with materials that won't corrode or require coatings
- Early supplier engagement to ensure manufacturability and reduce design iterations
- The new Doors and Beams design intent to be “drop-in” replacement
 - Assembly will prioritize reuse of existing unaffected components
 - No modifications of existing components/no machining
 - Simplifies upgrade in the field at Service Centers/Channel partners

Estimated Completion Date: ~2 years

% Completed: 10%

Source: GCC



Affected OEMs: Bombardier, Gulfstream, Embraer

Impacted Regions: Americas, APAC, EMEA

Initiator: Brian Reed

Owner: John Pursell

Initiation Date: April 2024

Moved to Top 25: April 24

Original Commit Date: NA

Problem Description: Reports of GKN Inlet Mesh Peeling**Estimated Completion Date:** TBD

% Completed:

Source: GCC

Criteria to Close: Understand field issues and determine root cause and any corrective action**Status & Dates:**

- Inlet screen peeling addressed by GKN technical variance GKN-TV-9020E Allows repair of inlet peeling 360 around inlet circumference
- Inlet Barrel Screen Blistering, GKN introduced a redesign of the screen installation in Mid 2018
 - Prevents contact between stainless steel mesh screen and aluminum honeycomb

**Inlet Screen Peeling at Leading Edge****Inlet Barrel Blistering**

No Events or data has been provided to HON engineering
Need help with go forward efforts or close RAIL item 1087

Affected OEMs: Bombardier, Gulfstream, Embraer**Impacted Regions:** America, EMEA, APAC

RAIL Top 25 1088- AS907 Harnesses, Request for Field Repair

Initiator: Brian Reed

Owner: John Pursell

Initiation Date: April 2024

Moved to Top 25: April 24

Original Commit Date: NA

Problem Description:

Request Field Repair for Wire Harnesses

Criteria to Close:

LMM Revision


Status & Dates:

- Outer braid repair created for W3 harness
 - Damage from Fan Cowl Door hold open rod
 - SB 76-9033 released January 2025
- Outer braid repair for all wire harnesses
 - LMM revision to harness inspection / check created
 - Refers to Repair Manual for outer braid repair
 - Applies self-adhering silicone tape
 - Will be incorporated as each LMM is revised
- Field electrical repairs: Not allowed / advised

Estimated Completion Date: Q4 2025

80% Completed: NA

Source: GCC



Affected OEMs: Bombardier,
Gulfstream, Embraer, Textron

Impacted Regions: America, EMEA,
APAC

RAIL Queue 1089-AS907 Diffuser V-Seal (low time)

Initiator: GCC

Owner: John Pursell

Initiation Date: April 2024

Moved to Top 25: NA

Original Commit Date: NA

Problem Description:

- Field reports of Diffuser "V" seal separation results in AOG situations due to V seal piece lodging in anti-ice valve
- V seal had issue in 2017 – 2019 and was corrected
- Issue has reappeared

Criteria to Close:

Introduce Corrective Action


Status & Dates:

- Chief Engineer has requested complete, in-depth review of V seal interfaces, materials, design intent, temperatures, growth, etc.
- Initial actions have been initiated.
- Timeline of events since initial redesign created
- Will be long term, throughout 2025

Estimated Completion Date: TBD

20% Completed: NA

Source: GCC



Affected OEMs: Bombardier,
Gulfstream, Embraer, Textron

Impacted Regions: Americas, EMEA,
APAC

RAIL **Mechanical Queue** 1090-AS907 Anti-Ice Switch (New Switch Availability)

Initiator: GCC

Owner: John Pursell

Initiation Date: April 2024

Moved to Top 25: NA

Original Commit Date: NA

Problem Description:

Anti-ice switch redesign update

Criteria to Close:

Introduce redesigned switch

Status & Dates:

- Anti ice valve (ASC) investigated and given green light
- Cause of field events related to anti-ice switch PN WBA3020G103-007
- Investigation determined issue is with activation mechanism
 - Will activate, but not de-activate
- Issues with mechanism identified and redesign identified
 - PN to roll to -009
 - Proving a challenge
 - Unforeseen repeatability issue – delay
 - Target Q1 2026 for availability

Interim Actions:

- Increased production test from 500 to 1000 cycles
- Validates electrical circuit in addition to mechanical mechanism
- Interim actions have screened out infant mortality issue – low time removals almost non-existent

Estimated Completion Date: Q3 2025

% Completed: 70

Source: GCC



Affected OEMs: Bombardier, Gulfstream, Embraer

Impacted Regions: Americas, EMEA, APAC

RAIL **Mechanical Queue** 1091-AS907-3-1E Chip Zap CAS Message Clearing

Initiator: Aaron Edwards

Owner: Yvan Lajoie

Initiation Date: April 2024

Moved to Top 25: NA

Original Commit Date: NA

Problem Description:

CAS message is cleared after an ECU power down and back up.

Criteria to Close:

Investigate the AS907-3-1E ECU SW logic for the Chip Zap function

Status & Dates:

- Chip zap counts 20 successful or 5 unsuccessful chip zaps before posting a CAS message (ENGINE OIL CHIP)
 - Counters are not dependent on number of flights or ECU power cycles
 - Counters can only be “reset” with an ECU download
- CAS message will annunciate in cockpit after an ECU power cycle and after the engine is started and has reached ground idle
 - CAS is inhibited during all phases of flight
 - Starts at TO roll of 80 knots
 - Ends at touchdown (AC speed drops to 30 knots) + 30 seconds
- Chip Zap logic is identical in all current AS907 ECU software
- Above functions certified with the FAA and verified with engineering system bench testing in November 2024 for the AS907-3-1E SW version

Needs Update

Estimated Completion Date: TBD

% Completed: NA

Source: GCC



Affected OEMs: Embraer

Impacted Regions: Americas

RAIL **Mechanical Queue** 1093- EEI for Forge vs. EEI 3.0 Synchronized Functionality

Initiator: Kellen Bush

Owner: John Pursell

Initiation Date: April 2024

Moved to Top 25: NA

Original Commit Date: NA

Problem Description:

EEI for Forge does not have the same functionalities as the e-Engine Interface (EEI) software version 3.0

Criteria to Close:

Update EEI for Forge

Status & Dates:

- The Honeywell Forge development team is working on several projects to improve the Forge EDV portal
- The new version provides a conversion tool to convert .TAR.GZ to .DLD (EEI 3.0 format)
- Forge 1.9.0 has been released and waiting on SIL approval to publish on the Aerospace portal

Estimated Completion Date: TBD

% Completed: NA

Source: GCC



Affected OEMs: Bombardier, Gulfstream, Embraer, Textron

Impacted Regions: Americas

RAIL **Mechanical Queue** 1094- AS907-3-1E MCID 133 Nuisance vs HMU Replacement

Initiator: Aaron Edwards

Owner: Yvan Lajoie

Initiation Date: April 2024

Moved to Top 25: NA

Original Commit Date: NA

Problem Description:

MCID 0133 OMS Message: Fuel System HMU Suspect and the associated CAS message ENG 1 or 2 SHORT dispatch, remove and replace the HMU per LMM instructions

Criteria to Close:

- Improve HMU spares availability
- Review troubleshooting techniques and possible contributing causes


Status & Dates:

- Review and analyze EEI files – ongoing
- Review HMU P/N 442650 shop findings - 2Q2025

Estimated Completion Date: TBD

% Completed: NA

Source: GCC



Affected OEMs: Embraer

Impacted Regions: Americas

HONEYWELL **APPENDIX FOR 1094**

YVAN LAJOIE
HTF PRODUCT SUPPORT ENGINEER

April 25, 2025


Honeywell

EEI REVIEW ENGINE P131161 – MCID 0133 ON 12/13/2024

Aircraft ID	Engine S/N	Engine Position	Data Start Date	Data Start Time	Download Date	Download Time
31	P131161	Right	12-12-23	07:03:52	12-13-23	


Parameter	First Occurrence	Last Occurrence
MC Flight Number	1049	1049
MC GMT Date	12-12-23	12-13-23
MC GMT Time	05:38:57	08:38:47
MC Flight Ground	1	1

Parameter	First Occurrence	Units
MC Altitude	195	ft
MC CAS	0.75	knots
MC TAT	6.01	C
MC N1	20.70	%
MC N2	51.20	%
MC EGT	335.07	C
MC CGV position	54.54	deg
MC TLA	19.31	deg
MC Fuel Flow Meter	374.69	PPH
MC ADC Average TT2	5.64	C
MC ITT	345.68	C
MC TS	5	
MC Latitude	53.05	N
MC Longitude	8.78	E
MC ECU Operating Time	8477:38:26	




MMV current null MCID 133 occurs at time 05:38:57 after engine start complete

EEI REVIEW ENGINE P131161 – MMV & TM CURRENT



AS907-3-1E/P131161 - HMU fault MCID 0133
12/13/2023




Fault occurs after start (38 secs for the above event)

EEI REVIEW ENGINE P131161 – MCID 0133 ON 4/11/2024

Aircraft ID	Engine S/N	Engine Position	Data Start Date	Data Start Time	Download Date
55000031	P131161	Right	03-22-24	13:10:24	04-15-24


Parameter	First Occurrence	Last Occurrence
MC Flight Number	1109	
MC GMT Date	04-11-24	
MC GMT Time	13:56:58	
MC Flight Ground		

Parameter	First Occurrence	Units
MC Altitude	-367	ft
MC CAS	2.73	knots
MC TAT	21.85	C
MC N1	23.80	%
MC N2	56.06	%
MC EGT	372.56	C
MC CGV position	54.49	deg
MC TLA	19.31	deg
MC Fuel Flow Meter	400.13	PPH
MC ADC Average TT2	20.39	C
MC ITT	394.07	C
MC TS	6	
MC Latitude	32.36	N
MC Longitude	-64.67	E
MC ECU Operating Time	8721.14	13




MMV current null MCID 133 only latched at time 13:58:59

EEI REVIEW ENGINE P131161 – MMV & TM CURRENT



AS907-3-1E/P131161 - HMU fault MCID 0133
04/15/2024



MMV torque motor current Null total time duration 21 seconds


Aircraft ID	Engine S/N	Engine Position	Data Start Date	Data Start Time	Download Date	Download Time
9H-AFX	131158	Right	05-09-22	08:45:00	06-19-22	08:45:00

Code	Flights	Occurrences	Status	Last Date	Last Time	Description
1522	0	19	Current	06-17-22	03:45:03	MC-1522 ARINC Receiver Fault ARI 3B
1523	0	20	Current	06-17-22	03:45:03	MC-1523 ARINC Receiver 1A
1524	0	20	Current	06-17-22	03:45:03	MC-1524 ARINC Receiver 1B
1525	0	19	Current	06-17-22	03:45:03	MC-1525 ARINC Receiver 3A
1526	0	19	Current	06-17-22	03:45:03	MC-1526 ARINC Receiver 3B
1505	0	2	Current	05-31-22	11:11:09	MC-1505 Aircraft ARINC system
133	0	1	Current	00:00:00	00:00:00	MC-133 Fuel system HMM Suspect
1516	0	1	Current	00:00:00	00:00:00	MC-1516 Aircraft ARINC system

Parameter	First Occurrence	Last Occurrence
MC Flight Number	582	...
MC GMT Date	06-19-22	...
MC GMT Time	07:00:47	...
MC Flight Ground	1	...


Reset Parameter	Time
MC Reset GMT Time	00:00:00
MC Reset GMT Date	00:00:00
MC ECU Reset Time	00:00:00

Parameter	First Occurrence	Units
MC Altitude	559 ft	
MC CAS	0.27 knots	
MC TAT	14.66 C	
MC N1	23.41 %	
MC N2	55.05 %	
MC EGT	352.93 C	
MC CGV position	54.46 deg	
MC TLA	13.98 deg	
MC Fuel Flow Meter	376.87 PPH	
MC ADC Average T12	13.85 C	
MC ITT	372.13 C	
MC TS	6	
MC Latitude	49.36 N	
MC Longitude	0.16 E	
MC ECU Operating Time	13027:51:05	




Honeywell | Global Customer Committee

EEI REVIEW ENGINE P131158 – MMV & TM CURRENT



MMV torque motor current Null total time duration 21 seconds after engine start complete

AS907-3-1E P131158 - HMU fault MCID 0133
6/19/2022



HMU S/N 1605 RETURN FOR REPAIR – NO INCOMING TEST

P/N 442650 S/N FHC1605 [RCVD_COND]MISSING ALL PORT SHIPPING CAPS. RECEIVING VISUAL INSPECTION REVEALED NO DAMAGE TO THE EXTERIOR OF THE UNIT DUE TO O/H WORKSCOPE REQUESTED BY THE CUSTOMER, **RAR TESTING HAS BEEN WAIVED**. SEALS WERE OEM INCOMING PUMP PN 2688676 S/N 15ANL1719. H536868 RW 02/29/24.

[WORK_ACCOMPLISHED]DISASSEMBLY & CLEANING COMPLETED IAW 73-20-33 REV 1. H536868 RW 03/01/24.

===== ANALYTICAL COMPLETED IAW 73-20-33 REV 1. H536868 RW 03/01/24. ===== [CAUSE_LONG_TXT]

OVERHAUL [REMV_TYPE]SCHEDULED

***RAR = Run As-Received

LIGHT MAINTENANCE MANUAL AS907-3-1E (72-05-19) Chapter 05-20-00 Inspections For Every (see below table) Engine Operating Hours Inspection Details Refer to [Paragraph 2.P. Periodic Inspections \(Subtask 72-00-00-200-015-A01\)](#) Step (6). and CMM, report No. 73-20-31.

1. Do a complete inspection of the HMU. The inspection includes the component disassembly, cleaning, inspection, assembly and test***.

NOTES: *** HMU (integral fuel control and fuel pump). The fuel pump and HMU component card(s) need to be removed from the engine log book and attached to the HMU when returning the components for the XXXX hour inspection

Engine	OEM	LMM Interval	LMM + permitted additional Hrs
AS907-1-1A	Bombardier	7,200 Hrs	7,800 Hrs
AS907-2-1A	Bombardier	7,200 Hrs	7,800 Hrs
AS907-2-1G	Gulfstream	7,200 Hrs	7,800 Hrs
AS907-2-1S	Textron	7,000 Hrs	7,800 Hrs
AS907-3-1E	Embraer	7,000 Hrs	7,750 Hrs

SFDC CASE-27948144: Hello, here is another Praetor with HMU MCID-133 faults. These events seem to all happen right at the first engine start of the day. The engine start time for this event was 18:43:07z the fault happened at 18:43:40z. What are your thoughts on troubleshooting this and no recent history other than reboots? One other point is the flip flopping of faults from short dispatch to no dispatch???? That seems to be a pattern also. Thank You

History:2/15/2024 Cyan (ENG 1 SHORT DISPTACH) on engine start. Mel’ed.

Honeywell e-Engine Interface [Maintenance Conditions]

File Name: 131307_907_021524_234336_a.dld

Aircraft ID: N417FX Engine Serial Number: 131307

Engine Position: Left ECU Channel: A

Download Date: 02-15-24 Download Time: 23:38:59

Code Flights Occurrences Status Last Date Last Time

133 0 2 Current 02-14-24 13:38:14

Description: MC-133 Fuel system HMU Suspect

Maintenance Condition Data:

Parameter First Occurrence Last Occurrence

MC Flight Number 2403 2414

MC GMT Date 02-07-24 02-15-24

MC GMT Time 03:39:44 18:43:40

MC Flight Ground 1 1

2/14/2024 Cyan (ENG 1 NO DISPTACH) on engine start. **Rebooted and cleared.**

Honeywell e-Engine Interface [Faults]

File Name: 131307_907_021524_234336_b.dld

Aircraft ID: N417FX Engine Serial Number: 131307

Engine Position: Left ECU Channel: B

Download Date: 02-15-24 Download Time: 23:43:35

Functional Fault Summary:

FF Fault ID Description Date Time

256 Local channel fuel torque motor null shift indicated 02-07-24 03:39:56

458 FF-256;Local channel fuel torque motor null shift indicated; FF- 257; Cross channel fuel torque motor null shift indicated 02-07-24 03:39:56

257 Cross channel fuel torque motor null shift indicated 02-07-24 03:39:44

Honeywell e-Engine Interface [Chronology]

File Name: 131307_907_021524_234336_b.dld

Aircraft ID: N417FX Engine Serial Number: 131307

Engine Position: Left ECU Channel: B

Download Date: 02-15-24 Download Time: 23:43:35

Data Chronology:


18:43:40 02-15-24 _ MC ID: 133

2/06/2024 Cyan (ENG 1 NO DISPTACH) and (ENG 1 SHORT DISPTACH) on engine start. **Rebooted and cleared.**

5/18/2023 Cyan (ENG 1 SHORT DISPTACH) on engine start. **Rebooted and cleared.**


See next slides for EEI detail information

EEI REVIEW ENGINE P131307 – MCID 133




MMV current null MCID 133 occurs 8 secs after engine start complete

EEI REVIEW ENGINE P131307 – MMV & TM CURRENT



AS907-3-1E/P131307 - HMU fault MCID 0133




Typically occuring after start (38 secs for the above event)

HMU S/N FHC2074 RETURN FOR REPAIR – NO FINDINGS IN HAVREL


SHORT DISPATCH HMU CAS MESSAGE, 5895.8 /1116.4, TAIL #N417FX,EMBRAER LEGACY 500
[REMV_TYPE]UNSCHEDULED[RMV_REASON_CD_DESC]OTHER (DESCRIBE IN REMARKS)

EEI REVIEW 1/9/2025 - ENGINE P131816 – MCID 133 DUAL CHANNEL RESULTED IN A NO DISPATCH CAS MESSAGE



MMV current null MCID 133 occurs 9 secs after engine start complete

MCID 133 – DUAL CHANNEL FAULT



Local and cross channel fuel torque motor null shift indicated


MCID 133 – LOCAL CHANNEL SINGLE FAULT

View Current Maintenance Conditions							View History Maintenance Conditions						
Code	Flights	Occurrences	Status	Last Date	Last Time	Description							
1803	0	2	Current	12-07-24	14:22:31	MC-1803 Unexpected channel swap							
1813	0	3	Current	12-07-24	14:22:31	MC-1813 Powerplant event record							
133	0	2	Current	12-07-24	14:22:30	MC-133 Fuel system HMMU Suspect							
1505	0	28	Current	11-11-24	13:52:43	MC-1505 Aircraft ARINC system							
1490	0	4	Current	11-07-24	17:34:51	MC-1490 ECU -B idle lock system							
1515	0	4	Current	09-26-24	19:22:07	MC-1515 Aircraft ARINC system							
1508	0	2	Current	09-06-24	17:22:36	MC-1508 ARINC receiver 1A							
1510	0	2	Current	09-06-24	17:22:36	MC-1510 ARINC receiver 1B							

Maintenance Condition Details						
Maintenance Condition Data				Operational Data		
Parameter	First Occurrence	Last Occurrence		Parameter	First Occurrence	Last Occurrence
MC Flight Number	1872	1883		MC Altitude	-50 ft	94 ft
MC GMT Date	12-03-24	12-07-24		MC CAS	1.28 knots	0.00 knots
MC GMT Time	16:45:54	14:22:30		MC TAT	15.54 C	7.28 C
MC Flight Ground	1	1		MC N1	20.90 %	20.54 %

Maintenance Reset Data			
Reset Parameter	Time		
MC Reset GMT Time	00:00:00		
MC Reset GMT Date	00:00:00		
MC ECU Reset Time	00:00:00		


Parameter	First Occurrence	Units	Last Occurrence	Units
MC Altitude	-50 ft		94 ft	
MC CAS	1.28 knots		0.00 knots	
MC TAT	15.54 C		7.28 C	
MC N1	20.90 %		20.54 %	
MC N2	51.74 %		51.25 %	
MC EGT	379.19 C		368.17 C	
MC CGV position	54.54 deg		54.54 deg	
MC TLA	19.20 deg		19.20 deg	
MC Fuel Flow Meter	364.10 PPH		371.04 PPH	
MC ADC Average TT2	13.40 C		7.09 C	
MC ITT	394.83 C		381.59 C	
MC TS	5		5	
MC Latitude	30.18 N		30.18 N	
MC Longitude	-97.66 E		-97.66 E	
MC ECU Operating Time	6479:05:46		6514:15:32	



Local channel fuel torque motor null shift indicated

HMU REMOVALS PER AIRCRAFT MODEL 3-MONTH PERIOD

MCID 133 - Oct 2024 to Feb



Challenging to gather all the required information Date, ESN, MSN, HMU S/N & SFDC case number to correlate shop findings versus the aircraft fault MCID 133.

Unit S/N 3171, Electrohydraulic SERVO VALVE (MV EHSV) P/N 2718972 was replaced during shop visit. The HMU was returned in December 2024 for CAS message - ENG 2 NO DISPATCH

PART_SERIAL	DESC	WORK_ACCOMPLISHED_TEXT
FHC2148	FAULT CODE 0133	[REMV_TYPE]UNSCHEDULED[RMV_REASON_CD_DESC]OTHER (DESCRIBE IN REMARKS)
FHC3171	RH ENG SHORT DISPATCH CAS WITH MCID 0133 (DETECTION OF SUSPECT OPERATION WITHIN THE HMU).OEM HMU, TSN: 471 HOURS	[WORK_ACCOMPLISHED]REPAIR COMPLETED IAW CMM 73-20-33. REMOVED FMV EHSV LOOL IAW CMM 73-20-33 REV 1, 20-FEB-25 ANALYTICAL COMPLETED IAW 73-20-33 REV [CAUSE_LONG_TXT] DURING RAR THE FOLLOWING TEST POINTS WERE OUT OF SPEC LIMITS: * T/P 410 LOOL, CHECK SHIMMING IN HIGH PRESSURE PUMP RELIEF VALVE * T/P 675B LOOL, ADJUST AT FINAL * T/P 730A LOOL, REPLACE FMV EHSV * T/P 720B LOOL, REPLACE FMV EHSV * T/P 730B LOOL, REPLACE FMV EHSV * ALL OTHER TEST POINTS MET SPECIFICATION LIMITS. * RH ENG SHORT DISPATCH CAS WITH MCID 0133 (DETECTION OF SUSPECT OPERATION WITHIN THE HMU)UNSCHEDULED [RCVD_COND]RECEIVING VISUAL INSPECTION FOUND MISSING SHIPPING BLOCK/PAD, ELECTRICAL COVER AND INLET COVER/2 SCREWS,2 WASHERS. REPLACED PRIOR TO DISASSEMBLY. SEALS WERE OEM INCOMING PUMP PN 2688676 S/N 18ANL2405, 20-FEB-25[WORK_ACCOMPLISHED]DISASSEMBLED & CLEANED IAW CMM 73-20-33 REV 1 , 20-FEB-25 ANALYTICAL COMPLETED IAW CMM 73-20-33 REV
FHC2324	FAULT CODE MC-133 RELATED TO HMU INTERNAL FAILURE.	[ACTION]OVERHAULED[RCVD_COND]RECEIVING VISUAL INSPECTION FOUND RAISED METAL AND SCRATCHES ON MOUNTING SURFACE. SEALS WERE OEM INCOMING PUMP PN 82011224-001 SN 150329-0693, 19-FEB-25[WORK_ACCOMPLISHED]OVERHAUL COMPLETED IAW CMM 73-20-33. DISASSEMBLED AND CLEANED IAW CMM 73-20-33 REV 1, ANALYTICAL COMPLETED IAW CMM 73-20-33 REV, 21-FEB-25 [CAUSE_LONG_TXT] ENGINE 1 SHORT DISPATCHCASMESSAGEMC133FUELSYSTEM[REMV_TYPE]UNSCHEDULED[RMV_REASON_CD_DESC]OTHER (DESCRIBE IN REMARKS)
FHC3142	ENGINE 1 SHORT DISPATCH CAS MESSAGE MC-133 FUEL SYSTEM	[WORK_ACCOMPLISHED]THE INSPECTION/REPAIRS WILL BE ACCOMPLISHED BY OUR VENDOR. THE FINDINGS WILL BE PROVIDED UPON COMPLETION [CAUSE_LONG_TXT] THE INSPECTION/REPAIRS WILL BE ACCOMPLISHED BY OUR VENDOR. THE * FINDINGS WILL BE PROVIDED UPON COMPLETION [REMV_TYPE]UNSCHEDULED[RMV_REASON_CD_DESC]OTHER (DESCRIBE IN REMARKS)
FHC2175	HMU TORQUE MOTOR NULL SHIFT CAUSING SHORT DISPATCH CAS MESSAGE MC-133	

MCID 133 predominantly reported on the Embraer Praetor

RAIL Queue 1095- AS907 W3 Harness Hold Open Rod Interference

Initiator: GCC

Owner: John Pursell

Initiation Date: April 2024

Moved to Top 25: NA

Original Commit Date: NA

Problem Description:

Fan cowl door hold open rod may chafe W3 harness over braid

Criteria to Close:

Introduce corrective action

Status & Dates:

- **Service bulletin 76-9033 released Q1 2025**
- Provides for application of anti-chafe sleeve (spiral wrap) and reposition of clamp to ensure adequate harness-to-hold open rod clearance
- Side Bar... Procedures to inspect cloth over-braid and apply anti-chafe sleeve will be added to LMMs and expanded to other areas of the harnesses

Estimated Completion Date: TBD

% Completed: 100

Source: GCC



Recommend Closure of this RAIL Item

Affected OEMs: Bombardier, Gulfstream, Embraer, Textron

Impacted Regions: Americas