

PROTECT YOURSELF FROM A POTENTIAL \$300,000 MAINTENANCE COST!



**Honeywell's original DU-1310
Dassault EASy Cockpit displays
(p/n 7028140-901/-905)
can no longer be repaired.**

If your aircraft is equipped with the legacy DU-1310 displays we encourage you to sign up for our HAPP DU-1310 Extended Coverage. Once covered should you experience a display failure, Honeywell will cover the cost for the replacement of both displays with newer units.

- The HAPP DU-1310 Extended Coverage can be added to your existing or new HAPP contract.
- Sign up now to take advantage of special 2016 pricing and pay just \$15 per flight hour per display on top of your existing HAPP contract.
- Sign up now and for just \$15 per flight hour you'll be protected from potential unplanned maintenance costs of up to \$300,000.

As a HAPP customer you'll also experience complete peace of mind, secure in the knowledge that should the unexpected happen, you won't end up with a large unbudgeted cost. You can also count on Honeywell and our network of authorized avionics service centers to get you back in the air — fast.

To sign up for our HAPP DU-1310 Extended Coverage, please contact your preferred avionics dealer or email us directly at happ-sales@honeywell.com; alternatively visit aerospace.honeywell.com/HAPP.