

PROTECT YOURSELF FROM POTENTIAL HIGH MAINTENANCE COST!

Maintenance Service Plan – Avionics
Extended Coverage for ED800



If your aircraft is equipped with the legacy ED800 display, we encourage you to sign up for our Maintenance Service Program (MSP) – Avionics Extended Coverage program. The displays can no longer be repaired and are no longer covered under the standard MSP – Avionics plan for unwarranted exchanges. Once covered, should you experience a display failure, Honeywell will cover the replacement cost for a new CMA6800 display.

**Honeywell's original
Electronic Displays
ED800 (7003110-9XX)
can no longer be repaired.**

The MSP – Avionics Extended Coverage for ED800 can be added to your existing or new MSP – Avionics contract.

- Enroll now for a flight hour rate on top of your existing MSP – Avionics contract.
- You will be protected from high unplanned maintenance costs.
- You will benefit from stable, predictable costs that enable financial planning and predictability, together with a higher aircraft dispatchability rate as a result of fast turn-around of replacement parts dispatched from worldwide stocking locations.

As a Maintenance Service Plan customer, you'll also experience complete peace of mind, secure in the knowledge that you won't end up with a large unbudgeted cost. You can also count on Honeywell and our network of authorized avionics service centers to get you back in the air – fast.

To sign up for MSP – Avionics Extended Coverage program for ED800, please contact your preferred avionics dealer or email us directly at:
MSPAvionicsSales@honeywell.com.

Honeywell Aerospace
1944 East Sky Harbor Circle
Phoenix, AZ 85034
aerospace.honeywell.com

N61-2410-000-000 | 02/20
2020 Honeywell International Inc.

**THE
FUTURE
IS
WHAT
WE
MAKE IT**

Honeywell